

Drainage Assets - Visual Inspection Report



ACA Ref / Condition Survey Date
 Asset Type Inspected by Rating Report Date

Inspection Item	Defect	Quality	Safety	Score	Comment
Atmosphere				0	
Cover and frame				0	
Bedding to frame				0	
Fabric of chamber				0	
Access ladder/step irons				0	
Inlet pipe free flowing				0	
Outlet pipe free flowing				0	
Number plate				0	
Signs of contamination				0	

Asset Construction Chamber size (L x W x D) X X
 Depth of water (mm) Silt depth (mm) Needs cleaning
 Cover type/material Cover condition Mesh leaf/guard
 Comments


Drainage Assets

In	Ref	Invert	Depth	Diameter	Material
	A		1200	300	Corricated Iron
	B				
	C				
	D				
	E				

Out	Ref	Invert	Depth	Diameter	Material
	X		1200	300	Corrigated Iron (Bunged Off)
	Y				
	Z				

Location

Cover Level



Images

